HAB5 NY, 40-PAT, 2-G-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Hayt Farmstead, Barn Route 311 Patterson Putnam County New York

NY-6300-G-8

HABS No. NY-6300-G

2, 2, 1, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2,	
Photographer:	Rob Tucher February 1989
NY-6300-G-1	VIEW TO EAST
NY-6300-G-2	VIEW TO SOUTH
NY-6300-G-3	VIEW TO NORTHEAST; BARN IS TO LEFT, ATTACHED STABLE TO RIGHT
NY-6300-G-4	VIEW TO NORTHWEST, STABLE IN FOREGROUND
NY-6300-G-5	VIEW TO WEST
NY-6300-G-6	INTERIOR VIEW TO SOUTH WALL OF BARN, SHOWING FRAMING
NY-6300-G-7	INTERIOR VIEW OF MILKING STANCHIONS IN BASEMENT AREA, SOUTHEAST CORNER OF BARN

INTERIOR VIEW TO SOUTH, SHOWING STALLS IN STABLE